§§ 52.1924-52.1927

CEMS as required in this section, the owner or operator shall comply with the following requirements:

- (1) For each emissions limit in this section, comply with the notification, reporting, and recordkeeping requirements for CEMS compliance monitoring in 40 CFR 60.7(c) and (d).
- (2) For each day, provide the total SO_2 emitted that day by each emission unit. For any hours on any unit where data for hourly pounds or heat input is missing, identify the unit number and monitoring device that did not produce valid data that caused the missing hour.
- (g) Equipment Operations. At all times, including periods of startup, shutdown, and malfunction, the owner or operator shall, to the extent practicable, maintain and operate the unit including associated air pollution control equipment in a manner consistent with good air pollution control practices for minimizing emissions. Determination of whether acceptable operating and maintenance procedures are being used will be based on information available to the Regional Administrator which may include, but is not limited to, monitoring results, review of operating and maintenance procedures, and inspection of the unit.
 - (h) Enforcement.
- (1) Notwithstanding any other provision in this implementation plan, any credible evidence or information relevant as to whether the unit would have been in compliance with applicable requirements if the appropriate performance or compliance test had been performed, can be used to establish whether or not the owner or operator has violated or is in violation of any standard or applicable emission limit in the plan.
- (2) Emissions in excess of the level of the applicable emission limit or requirement that occur due to a malfunction shall constitute a violation of the applicable emission limit.

 $[76 \; \mathrm{FR} \; 81758, \; \mathrm{Dec.} \; 28, \; 2011]$

§§ 52.1924–52.1927 [Reserved]

§52.1928 Visibility protection.

(a) The following portions of the Oklahoma Regional Haze (RH) State

Implementation Plan submitted on February 19, 2010 are disapproved:

- (1) The SO₂ BART determinations for Units 4 and 5 of the Oklahoma Gas and Electric (OG&E) Muskogee plant; Units 1 and 2 of the OG&E Sooner plant; and Units 3 and 4 of the American Electric Power/Public Service Company of Oklahoma (AEP/PSO) Northeastern plant;
- (2) The long-term strategy for regional haze:
- (3) "Greater Reasonable Progress Alternative Determination" (section VI.E), and
- (4) Separate executed agreements between ODEQ and OG&E, and ODEQ and AEP/PSO entitled "OG&E Regional Haze Agreement, Case No. 10–024, and "PSO Regional Haze Agreement, Case No. 10–025," housed within Appendix 6–5 of the RH SIP.
- (b) The portion of the State Implementation Plan pertaining to adequate provisions to prohibit emissions from interfering with measures required in another state to protect visibility, submitted on May 10, 2007 and supplemented on December 10, 2007 is disapproved.
- (c) The SO₂ BART requirements for Units 4 and 5 of the Oklahoma Gas and Electric (OG&E) Muskogee plant; Units 1 and 2 of the OG&E Sooner plant; and Units 3 and 4 of the American Electric Power/Public Service Company of Oklahoma (AEP/PSO) Northeastern plant, the deficiencies in the long-term strategy for regional haze, and the requirement for a plan to contain adequate provisions to prohibit emissions from interfering with measures required in another state to protect visibility are satisfied by §52.1923.

 $[76~{\rm FR}~81759,\,{\rm Dec.}~28,\,2011]$

§ 52.1929 Significant deterioration of air quality.

(a) Regulation for preventing significant deterioration of air quality. The Oklahoma plan, as submitted, does not apply to certain sources in the State. Therefore the provisions of §52.21 except paragraph (a)(1) are hereby incorporated, and made part of the Oklahoma State implementation plan, and are applicable to the following major stationary sources or major modifications: